



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

Report Date: September 20, 2006

Supervisor DRH

**Mine Name:** Moenkopi Moca  
**Operator Name:** Bruce H. Hansen Stone Quarries  
Noal Hansen  
1345 South Stewart Drive  
P.O. Box 341  
Kanab, Utah 84741-0341

**Permit number:** S/025/021  
**Date:** September 11, 2006  
**Time:** 7:45 AM

**Inspector(s):** Doug Jensen  
**Other Participants:** None  
**Mine Status:** Active

**Weather:** Cool

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Check the site while in the area.

**Directions to Site:**

See previous inspection memo

**Inspection Summary:**

The footprint of the quarry has not changed. The floor of the quarry has been deepened. Pictures were taken of the site and are included with this report.

**Conclusions and Recommendations:**

I will continue to monitor the site while in the area.

**Inspector's Signature**

Doug Jensen

**Date:** 9/20/06

dj:pb

cc: Noal Hansen  
John Blake, SITLA ML-47138

O:\M025-Kane\S0250021-MoenkopiMoca\inspections\09112006insp.doc







09.

09.12.2006 07:52




Mine Number: S0250021  
Mine Name: Moenkopi Moca  
Township 32 S Range 04 W Section 32 SLBM

Inspection Date Feb. 28, 2006  
Map Produced by DKS

Acres Disturbed	1.73
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0
Total Acres Disturbed	
1.73	
Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

- Legend**  
All items symbolized in legend may not be appear on map
- County Boundary
  - Access
  - Mine
  - NonMine
  - Other
  - Interstate
  - US Route
  - Slate Route
  - Primary Route
  - Secondary Route
  - Main Dirt Road
  - Unimproved Road
  - Interchange
  - Trail
  - Township or range line: location doubtful
  - Section line
  - Section line: location doubtful
  - Disturbed
  - Regraded
  - Seeded
  - Released
  - Excluded
  - Prelaw
  - Bond Area
  - SITLA Mineral Leases
  - BLM Subleases
  - Community Pft

DOQ imagery date 2004



Dept. of Natural Resources  
Division of Oil, Gas, and Mining  
Mineral Mines Program

Different data sources and input scales  
may cause misalignment of data layers.  
This product may not meet DOGM  
standards for accuracy and content.